

## Fabric-I lab

Exp. name: Traversie motion of pinn winding

Machine

Machine parts:

- (i) Motor
- (ii) Motor pully
- (iii) V-belt
- (iv) Machine pully
- (v) shaft
- (vi) V-pully
- (vii) Cam moving pully
- (viii) Cam box
- (ix) Straight cut gear-1
- (x) Straight cut gear-2
- (xi) Cam
- (xii) Cam ~~rod~~ connecting rod

(xiii) Key

(xiv) Traversal connecting nod +1

(xv) Traversal connecting nod -2

(xvi) T-løven

(xvii) Traversal body

(xviii) Traversal ben

