

Exp :- 03 Transverse motion of pitch winding


Machine .

M/c parts :

1. Motor pully
2. Motor
3. V-belt
4. m/c pully → Shaft
5. v- pully
6. Cam moving pully
7. Cam box
8. Straight cut gear, 1
9. " " " 2
10. Cam
11. Cam connecting rod
12. Key

13. Traverses connecting rod - 1

14. "



15. T-Lever

16. Traverses body

17. Traverses bar

