

Study on shifting mechanism of
pinion - pinion wending machine.
pinion.

- Parts name :
1. Cam box
 2. Straight cut gears
 3. Straight cut pinion
 4. Moving cam (up and down movement)
 5. Connecting rod
 6. V-lever.
 7. Pushing connecting rod.
 8. Pushing pawl
 9. Ratchet wheel
 10. Worm gears.
 11. Helical gears.
 12. Pinion 2nd
 13. Straight cut gear 2.
 14. Traverser Body